

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 2, 2012

	Notal 2
Reviewed:	99/1/

Mine Name: Gulch Mine	Permit Number: S/023/0087		
Operator Name: Wall & Rock Inc.	Inspection Date: March 29, 2012		
Inspector(s): Wayne Western	Time: 4:15-4:34 pm		
Other Participants: none	Mine Status: Active		
Weather Condition: Cool and windy	Last Inspection: April 21, 2011		
Bond Renewal Date: 12/08/2013	Bond Amount: \$11,700.00		
Surface Ownership: Fee	Mineral Ownership: Fee		
Annual Report Submitted: No	Permit Fees Paid: No		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds		\boxtimes	
2.	Annual Fees	\boxtimes		
3.	Public Safety (shafts, adits, trash, signs, highwalls)			
4.	Protection of Drainages / Erosion Control			
5.	Deleterious Material			
6.	Roads (maintenance, surfacing, dust control, safety)			
7.	Concurrent Reclamation			
8.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
9.	Water Impoundments			
10.	Soils			
11.	Re-vegetation			
12.	Air Quality			
13.	Annual Report	\boxtimes	\boxtimes	
14.	Other			

Inspection Date: March 29, 2012 Page 2 of 4 S/023/0087

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The annual reports have not been submitted to the Division. The last time activity on the site was documented on June 30, 2006. After five years of on inactivity, the Division can require reclamation.

Access to the site was blocked by berms placed at all access roads. Site can be access on foot.

The annual fees were not submitted for 2011

Abandoned vehicle that were photographed at the site had been removed. A large tire pile had been placed on site since the last inspection. The tire pile must be removed. A trackhoe which appears to be none working is still on site.

MC-2010-42-10, a violation for failure to provide adequate bond has not been closed. The NOV is part of a group settlement for other violations. As of date of inspection not all the conditions have been met.

Conclusions and Recommendations:

The Division should:

- Have the Permittee pay the permit fees
- Have the Permittee fill out the annual reports.
- Have the Permittee remove the tire pile from the site.

Inspector's Signature why

WHW:


cc: (OPERATOR)

agencies

O:\M023-Juab\S0230087-Gulch\inspections\Insp-02292012.doc



New tire pile. Picture taken March 29, 2012



Trucks were removed from the area where the tire pile is now. Picture taken April 21, 2011



Track hoe and barrel on site. Track hoe appears to be none functional.



Trash on site.